PAGE: 1

PRINT DATE: 01/09/90

. . . .

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 03-2A-201090-X

SUBSYSTEM NAME: AFT REACTION CONTROL SYSTEM (RCS)

REVISION: 2 01/09/00

PART NAME VENDOR NAME

PART NUMBER VENDOR NUMBER

LRU : DISCONNECT, QUICK, TEST

ME276-0032-0005

RR42670-5

LRU : DISCONNECT, QUICK, TEST

ME275-0032-0007

RR42670-7

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: DISCONNECT, QUICK, TEST POINT PROPELLANT SIDE (MD230, 231, 232, 233, 234, 235, 330, 331, 332, 333, 334, 335).

QUANTITY OF LIKE ITEMS: 12 6 POD

FUNCTION: TO PROVIDE ACCESS FOR CHECKDUT OF THE PROPELLANT TANK ACQUISITION SYSTEM.

PAGE: 2 PRINT DATE: 01/09/90 SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 03-2A-201090-01 2 01/09/90 REVISION# SUBSYSTEM: AFT REACTION CONTROL SYSTEM (RCS) LRU :DISCONNECT, QUICK, TEST CRITICALITY OF THIS ITEM NAME: DISCONNECT, QUICK, TEST FAILURE MODE::R3 FAILURE MODE: EXTERNAL LEAKAGE, POPPET FAILS OPEN MISSION PHASE: PRELAUNCH PL ŁO LIFT-OFF 00 ON-ORBIT Dô TIBRO-30 LANDING SAFING VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA : 103 DISCOVERY : 104 ATLANTIS CAUSE: SEALS DAMAGED OR DETERIORATED, VIBRATION, PIECE PART STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL SHOCK. IMPROPER USE, INADEQUATE MAINTENANCE OF GSE HALF, INADEQUATE LINE SUPPORT, SHAFT OR BORE BENT, DVERPRESSURIZATION OF PANEL, EXCESS TORQUE. CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO REDUNDANCY SCREEN A) FAIL B) FAIL C) PASS PASS/FAIL RATIONALE: A) 8) - FAILURÉ EFFECTS -(A) SUBSYSTEM: LOSS OF REDUNDANCY.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT

PAGE: 3 PRINT DATE: 01/09/90

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 03-2A-201090-01

- (C) MISSION: NO EFFECT
- (D) CREW, VEHICLE, AND ELEMENT(S): NO EFFECT
- (E) FUNCTIONAL CRITICALITY EFFECTS:

 POTENTIAL CREW/VEHICLE LOSS LOSS OF RCS ENTRY AND ET SEP PROPELLANT.

 LOSS OF HELIUM MAY ALSO OCCUR ON-ORBIT DUE TO ZERO GRAVITATIONAL

 EFFECTS. POSSIBLE LOSS OF VEHICLE CONTROL DURING ET SEP AND ENTRY.

 POSSIBLE DAMAGE TO STRUCTURE/TPS IF LEAKAGE OCCURS OR STRUCTURE AND

 ADJACENT HARDWARE IF CAP BLOWS OFF. LEAKAGE OF PROPELLANT VAPORS INTO

 POD. 1R EFFECT ASSUMES LOSS OF ALL SEALS (POPPET AND CAP) BEFORE

 EFFECT IS MANIFESTED. CANNOT CHECK REDUNDANT SEALS WHEN CAP IS

 INSTALLED. REQUIRES BOTH SEALS TO LEAK ON-ORBIT BEFORE FAILURE IS

 DETECTABLE.

- DISPOSITION RATIONALE -

(A) DESIGN:
EACH UNIT IS PROOF PRESSURIZED TO 2 X MAX OPERATING PRESSURE (700 PSI).
THE BURST PRESSURE DURING QUAL TESTING WAS 4 X MAX OPERATING PRESSURE (1400 PSI). A COMPLETE STRESS ANALYSIS WAS PERFORMED. GROUND HALF COUPLINGS AND LINES ARE SUPPORTED TO LIMIT STRESS ON COUPLINGS TO PREVENT DAMAGE TO SEALS AND WELD JOINTS. DUAL SEALING SURFACES WHEN THE CAP IS INSTALLED MINIMIZES LEAKAGE POTENTIAL.

THE GSE HALF COUPLING HAS A 10 MICRON FILTER TO PREVENT CONTAMINATION.

(B) TEST: NIME UNITS WERE USED IN THE QUALIFICATION TEST PROGRAM. HOWEVER, ALL TESTS WERE NOT PERFORMED ON ALL UNITS. THE PRIMARY QUALIFICATION METHOD WAS BY SIMILARITY TO APOLLO COUPLINGS.

TESTING ADDRESSED SPECIFIC CONCERNS RANDOM VIBRATION (POPPET OPEN AND CAP ON), ENDURANCE (400 CYCLES), THERMAL (+150 DEG F, -100 DEG F CERTIFIED BY MPS), PROPELLANT COMPATIBILITY AND BURST. THE UNIT WAS ALSO QUALIFIED AS PART OF THE POD ASSEMBLY IN THE VIBRO-ACOUSTIC TEST AT JSC (131 EQUIVALENT MISSIONS) AND THE HOT FIRE TEST AT WSTF (24 EQUIVALENT MISSION DUTY CYCLES AND APPROX 7 YEARS OF PROPELLANT EXPOSURE).

THE ACCEPTANCE TEST FOR EACH UNIT INCLUDED PROOF AND FUNCTIONAL, CLEANLINESS AND DRYING. TESTING OF THE CAP AT THE ASSEMBLY LEVEL, AND LEAKAGE CHECKS WITH AND WITHOUT THE CAP INSTALLED.

SHUTTLE CRITICAL ITEMS 11ST - ORBITER NUMBER: 03-2A-201090-01

OMRSD PERFORMS THE FOLLOWING: LEAK CHECKS ON THE QD COUPLING EVERY FIVE FLIGHTS. ANY COUPLINGS USED DURING GROUND TESTING SHALL ALSO BE LEAK CHECKED. A TOXIC VAPOR LEAK CHECK OF THE PROPELLANT TANK THE FIRST FLIGHT AND ON A CONTINGENCY BASIS. AN EXTERNAL LEAKAGE VERIFICATION OF THE SYSTEM FOR THE FIRST FLIGHT AND ON A CONTINGENCY BASIS. STATIC AIR SAMPLE FOR MOD/POD THE SECOND FLIGHT AND EVERY FLIGHT THEREAFTER AND ON A CONTINGENCY BASIS. A PROPELLANT SAMPLE THE SECOND FLIGHT AND WHEN TANKS OR MANIFOLDS ARE DRAINED. AN INSPECTION OF THE CAP SEALS THE FIRST FLIGHT AND WHENEVER THE QD IS USED DURING TURNAROUND. LOADED PROPELLANT MEET THE REQUIREMENTS OF SE-S-0073.

(C) INSPECTION:
RECEIVING INSPECTION
RAW MATERIAL IS VERIFIED BY INSPECTION.

CONTAMINATION CONTROL
CLEANLINESS TO LEVEL 100 FOR MMH AND 100A FOR N204 IS VERIFIED BY
INSPECTION. CORROSION PROTECTION IS VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION
CRITICAL DIMENSIONS AND SURFACE FINISHES ARE VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION EXAMINATION OF LIP SEALS UNDER 14X TO 30X MAGNIFICATION IS VERIFIED BY INSPECTION.

CRITICAL PROCESSES
WELDING IS VERIFIED BY INSPECTION.

TESTING

SEAL SURFACE IS FREE OF CONTAMINATES PRIOR TO ENGAGEMENT WITH THE MATING HALF AND ENGAGING TORQUE ARE VERIFIED BY INSPECTION. ATP IS WITNESSED AND VERIFIED BY INSPECTION. SAMPLE WELDS ARE SECTIONED AND CHECKED FOR WELD PENETRATION ON A PLAN OF 1 SAMPLE PER 20 WELDS.

HANDLING/PACKAGING AND STORAGE ENVIRONMENTS ARE VERIFIED BY INSPECTION.

(D) FAILURE HISTORY:
CARS A10762 (WSTF), AD0162 (KSC), AC0519 (SUP), AC8608 (SUP):
SEVERAL CONTAMINATION INDUCED LEAKAGE FAILURES HAVE OCCURRED. LEAKAGE
WAS RELATIVELY MINOR. OMRSD SCREENS FOR LEAKAGE AFTER EACH USAGE AND
PRIOR TO INSTALLATION OF CAP.

CAR AC9143:

FOUR HIGH PRESSURE QD'S WERE REMOVED FROM 0V102 BECAUSE OF LEAKAGE.
ANALYSIS IDENTIFIED THE CAUSE TO BE DUE TO DISTORTED SEALS (CAR STILL

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 03-24-201090-01

OPEN. POSSIBLE KYNAR SEAL MMH COMPATIBILITY PROBLEM) CORRECTIVE ACTION CONCERNING THE POSSIBLE MATERIAL (KYNAR) INCOMPATIBILITY IS PENDING COMPLETION OF THE FAILURE AUGUSTS. ALL HIGH PRESSURE QD'S WILL BE VERIFIED TO BE NOT LEAKING BEFORE FLIGHT STS-26.

CAR AC9986:

THREE QD'S WERE REMOVED FROM OVIO2 BECAUSE OF LEAKAGE. ONE COUPLING LEAK WAS DUE TO METALLIC CONTAMINATION, MOST PROBABLY CAUSED BY USE OF FREON IN CLEANING PROCEDURES. ONE LEAKED BECAUSE OF A LARGE PIECE OF ALUMINUM TAPE AND THE OTHER LEAKED BECAUSE OF SMALL METALLIC PARTICLES EMBEDDED IN THE POPPET SEAL. CORRECTIVE ACTION FOR CONTAMINATION CONTROL WAS IMPLEMENTED AT KSC BY ADHERING TO THE OMRSD PARAGRAPHS SPECIFICALLY DETAILED TO PREVENT METALLIC NITRATE AND PARTICLE CONTAMINATION. ONLY IPA IS USED IN

CAR 5360 (DOWNEY):

CLEANING MMH COMPONENTS.

AFTER 375 ENDURANCE CYCLES LEAKAGE WAS EXCESSIVE. THE CAUSE WAS CONTAMINANT EMBEDDED IN THE POPPET SEAL. IT WAS CONCLUDED THAT THE PARTICLES WERE INTRODUCED WHILE, OR PRIOR TO, BEING INSTALLED IN THE TEST SET-UP. THERE WAS NO VISIBLE THREAD DAMAGE. CORRECTIVE ACTION - PROCEDURES FOR CONNECTING, DISCONNECTING, AND MAINTAINING CLEANLINESS; I.E. PURGING, DRYING, FILTER INSTALLATION, ENGAGEMENT/DISENGAGEMENT PROCEDURES, CLEANING AND LUBRICATION OF THREADS ARE TO BE IN ACCORDANCE WITH SPECIFICATION ML0310-032 TO PRECLUDE CONTAMINATION.

(E) OPERATIONAL USE:

REQUIRES MULTI-SEAL FAILURE BEFORE ACTION IS REQUIRED. IF FAILURE OCCURS PRIOR TO ET SEP USE CROSSFEED.

FOR NOTICEABLE LEAK RATES ON-ORBIT, DUMP ONBOARD PROPELLANT. USE CROSSFEED FOR ENTRY. THIS MAY NOT BE SUFFICIENT PROPELLANT FOR NOMINAL ENTRY. IF LEAK OCCURS DURING ENTRY USE FAILED SYSTEM DOWN TO ZERO PVT. SWITCH TO X-FEED FOR REMAINDER OF ENTRY.

- APPROVALS -

RELIABILITY ENGINEERING: F.E. BARCENAS DESIGN ENGINEERING : B. DIPONTI QUALITY ENGINEERING :. M. SAVALA . NASA RELIABILITY

NASA SUBSYSTEM MANAGER : NASA QUALITY ASSURANCE :